U.S. Private Perforations John V. Farwell Co. (circa 1908-1917)

In 1908, the John V. Farwell Company of Chicago, Illinois, a large dry goods organization, began using a new and faster means of doing their large number of mailings. This was accomplished by operating the affixing equipment that was made by the Schermack Mailing Machine Company, (formerly the Detroit Mailing Machine Company), of Detroit, Michigan, using the 1902 2-cent Shield issue.

The Farwell Company must have had a very large number of mailings because around 1910 they were doing about \$20,000,000 in sales. With Schermack Company charging 50 cents over the face value for each of their 3000 coil roll of stamps; it is no wonder that in early 1911 the Farwell Company must have felt that they could save money by perforating the same imperforate stamps in-house. Only 1-cent and 2-cent stamps would be perforated by the Farwell Company.

Tom Chambers, a Farwell employee, produced several types of perforations while he experimented making coil stamps similar to the Schermack Type III perforated stamps they were currently using. Their perforating machine used pins to make the holes. Even as late as 1937, these various types of perforations were known as Chambers perforations. They perforated full sheets of 400 then cut them into strips then made coils. The details of the mechanism were never fully disclosed.

There are five known groups of perforations, with each group having different sub-types.

Group 1 has two types. Group 2 to 5 sub-types are described by the number of holes above an un-perforated space and the number holes below that space, such as 2A3. The two different spacing sizes between the sets of holes, were made by removing pins from the perforating machine, are classified as A for 2.5mm and B for 4.5mm. Group 5 is only known with A spacing.

Because of possible faults in the perforation process, the pins either broke or were misplaced in the device creating examples of mixed classifications as well as a shifting of the alignment of perforations.

The Farwell perforation holes are all the same size, 1.5mm in diameter with 0.5mm spacing between them, but not along the entire length of the stamp, as noted above.

Group 1: 6 holes or 7 holes

Group 2: 2 holes over 3 or 3 holes over 2

Group 3: 3 holes over 4 or 4 holes over 3

Group 4: 4 holes over 4

Group 5: 5 holes over 4 or 4 holes over 5

The printing of the 1908-1909 and the 1910-1911 U.S. stamp issues had different spacing on the vertical rows of stamps. This was done because the Bureau of Engraving and Printing was having difficulty with paper waste due to unequal shrinking of the sheets because of wet printing process problems. They spaced part of the sheet with 3mm spacing and the rest at 2mm spacing. Therefore there are pairs, strips and blocks of these issues with varying spacing between 2mm and 3mm because of the continual shrinking of the paper. This is the reason why there are multiple listings of the same issue shown here.

U.S. Private Perforations John V. Farwell Co.

Plate Numbers found with different Types of John V. Farwell Co. Perforations and various P.O. Issues.

Included here are several covers with Farwell perforated stamps but not on Farwell Company envelopes. There are commercially used, and several seem to be from individuals, all of whom acquired Farwell perforated stamps by some means, either by special request or through a friend.

Sometime in 1917 Farwell stopped producing coils and went to United States government coils.

Farwell Company is known to have used sheets with the following plate numbers:


Group 1 Group 2 Group 2 Group 3 Group 3 Group 4 Group 5 Group 5	Type I-6 Holes-not known; Type 2A3-July 28, 1911; Type 3A2-June 27, 1911; Type 3A4-not known; Type 4A3-not known; Type 4A4-May 17, 1912; Type 4A5-not known; Type 5A4-not known;			Type I-7 Holes-May 24, 1911; Type 2B3-not known; Type 3B2-not known; Type 3B4-October 28, 1911; Type 4B3-October 7, 1911; Type 4B4-October 11, 1911;		
Type 2A3	Issue of 1910-1911	2 cent	5608			
Type 2B3	Issue of 1910-1911	1 cent 2 cent	5489 5608	5598 5624		
Type 4A	Issue of 1910-1911	1 cent 2 cent	5484 5619	5679	5709	
	Issue of 1912	1 cent 2 cent	5867 5740	6041 6151	7294 7501	7708
Type 4B	Issue of 1910-1911	1 cent 2 cent	5484 5619	5679 5624	5709	5715
	Issue of 1912	1 cent 2 cent	5831 5740	5785		
Type 4AB	Issue of 1910-1911	1 cent 2 cent	5679 5608	5624	5686	
	Issue of 1912	1 cent 2 cent	5831 5785	6041 6151		
Group 5	Issue of 1912	1 cent	6615			

U.S. Private Perforations John V. Farwell Co. (circa 1908-1917)

Schermack Period (1908-1911)

Prior to perforating its own stamps, the Farwell Company used affixing machine postage stamps provided by the Schermack Company

Early Schermack Usage Issue of 1906




Chicago, IL to New London, CT July 18, 1908

U.S. Private Perforations John V. Farwell Co. Schermack Period (1908-1911)

Late Schermack Usage
Issue of 1910-1911
Chicago, IL to Sherman, TX
Double Rate
May 2, 1911

John V. Farwell Co.
Group 1
6 Holes
Issue of 1910-1911

During the production of the various types of Farwell perforations there was some process or procedure that caused some form of shifting alignment of the perforations from column to column. Sometimes the shifting goes between .5 to 4 millimeters up and then down the same amount. There is not sufficient knowledge of the entire perforating process to have a firm reason for this occurrence. Shifted perforations are the norm in some groups.





Shifted Perforations



2.4 mm e




Shifted Perforations 3 mm e

John V. Farwell Co.

Group 1

7 Holes
Issue of 1910-1911

First Day of Use with this type of perforation




Shifted Perforations Chicago, IL to Perry, NY May 24, 1911

Private perforation miscuts as seen on envelopes and stamps may have been caused by poor staff handling or maybe production process jamming, this is only guess work.

John V. Farwell Co.

Group 2 Type 2A3 Issue of 1910-1911





Shifted Perforations



2.6 mm


Many Farwell envelopes have also been found with the stamp inverted on the envelope. Somewhat unusual for a business. Seems that someone might have found it easier to fit the roll of stamps into the affixing machine that way or it just did not matter to them.

Inverted



John V. Farwell Co. Group 2

Type 2B3
Issue of 1910-1911







2.3 mm e

(ex-Belasco)



3 mm

John V. Farwell Co.

Group 2 Type 2B3 Issue of 1910-1911



Shifted Perforations

Paul C. Denzin, a stamp dealer from Milwaukee, WI, having removed the above stamp from a destroyed Farwell envelope swore on November 15, 1945 that it was a genuine used Farwell Type 2B3 Issue of 1910-1911 stamp.

STATE OF WISCONSI	N) (SS
MILWAUKEE COUNTY	PAUL C. DENZIN on oath de-
Wis.; that the at Scott cat. #384,F over 3 perf. canc one broken by let	a stamp dealer at Milwaukee, tached 2¢ U.S.postage stamp, arwell private perf., 2 perf. celled with 7 straight lines, ters "ATION" was removed by and is guaranteed Farwell use.
	Vaule DEngin
Subscribed and switchis 15 day of	Morenty, 1945.
Notary Public, Mi	ilwaukee Co. Wisconsin

Notary Verification

John V. Farwell Co. Group 2 Type 2B3 Issue of 1910-1911



Chicago-Canal Station Cancel

DITA

e




2.2 mm e (ex-Agris)



3 mm

John V. Farwell Co. Group 2 Type 3A2 Issue of 1910-1911





2.1 mm e (ex-Belasco)



3 mm



3 mm

John V. Farwell Co. Group 2 Type 3A2 Issue of 1910-1911





e



3 mm e (ex-Grunin)



2.1-2.5 mm e (ex-Howard)




Guideline Strip Shifted Perforations 2.3-2.5 mm

John V. Farwell Co.

Group 2 Type 3A2 Issue of 1910-1911

Inverted




Shifted Perforations Chicago, IL to Wayside, WI June 27, 1911



John V. Farwell Co.
Group 2
Trans 3B2

Type 3B2 Issue of 1910-1911



There are very few examples of pairs with pasteups found or reported. However, several singles have been found on and off envelopes. There must have been pasteup "request" items from collectors and dealers but for some reason the requests were not always honored by the company.

Plate Cracks in Right Margin



Pasteup





3 mm



Guideline Pair 2.3 mm e (ex-Belasco)




2.4-3 mm e



Guideline Strip 2.8 mm

John V. Farwell Co. Group 3 Type 3B4 Issue of 1910-1911





e



e



2.3 mm




3 mm



Guideline Pair 2.7 mm

John V. Farwell Co.

Group 3 Type 4B3 Issue of 1910-1911







Shifted Perforations 2.4 mm



3 mm



2.1-2.9 mm

John V. Farwell Co. Group 3 Type 4B3 Issue of 1910-1911





Pasteup



2.3 mm e



3 mm



Guideline Strip 2.7-2.9 mm

John V. Farwell Co. Group 3 Type 4B3 Issue of 1910-1911

Earliest Known Use

Inverted




Chicago, IL October 7, 1911

John V. Farwell Co.

Group 3

Type 4B3 Issue of 1910-1911

Inverted




Chicago, IL to Wayside, WI


October 25, 1911

(ex-Howard)

Inverted




John V. Farwell Co. Group 4 Type 4A4 Issue of 1908-1909





Pair
2.6 mm
Guideline at Left

John V. Farwell Co. Group 4 Type 4A4 Issue of 1908-1909





Shifted Perforations 2.4 mm e



Shifted Perforations 2.8 mm

(ex-Belasco)

John V. Farwell Co.

Group 4
Type 4A4

Issue of 1910-1911



2.2 mm



Shifted Perforations 2.6 mm

e



Guideline Pair Shifted Perforations 2.7 mm

e

Different Shifting Positions



Shifted Perforations 2-3 mm e



Shifted Perforations 2-3 mm e

0



Guideline Strip Shifted Perforations 2.5 mm

John V. Farwell Co.
Group 4
Type 4A4
Issue of 1910-1911

.



Plate Number Margin Strip 2.6-2.8 mm

e



2.5-2.8 mm Plate Number Imprint A5679



Plate Number Margin Strip 3 mm

John V. Farwell Co. Group 4 Type 4A4 Issue of 1910-1911





Shifted Perforations 2.3 mm



Shifted Perforations 3 mm



Guideline Pair Shifted Perforations 2.3 mm

John V. Farwell Co.
Group 4
Type 4A4
Issue of 1910-1911



Shifted Perforations 3 mm Plate Number Imprint 5619



Arrow Guideline Strip Shifted Perforations 2.8-3 mm Stuck on Card

John V. Farwell Co.
Group 4
Type 4A4
Issue of 1910-1911



2.3-3 mm



3 mm e



Guideline Strip 2.2 mm

e

ex-Sheldon, Grunin



Guideline Strip 2.7-3 mm

John V. Farwell Co. Group 4 Type 4A4 Issue of 1912





Margin Plate Number 6041 Strip Shifted Perforations



Top Arrow Block

John V. Farwell Co.
Group 4
Type 4A4
Issue of 1912

One Cent Unsealed Circular Rate




Shifted Perforations Chicago, IL to Fostoria, OH May 17, 1912

(ex-Agris)

John V. Farwell Co.

Group 4 Type 4A4 Issue of 1912

Farwell Advertizing Envelope



Chicago, IL to Appleton, WI May 1913

John V. Farwell Co.
Group 4
Type 4A4
Issue of 1912


Farwell also obtained imperforated sheets of Chicago precancel stamps. Only the 1-cent issue of 1912 has been found with both Type 4A4 and Type 4B4 perforations.

One of Two Known



Precancel Chicago, IL


Only Known Precancel Usage
Chicago Precancel



Chicago, IL to Appleton, WI

John V. Farwell Co.

Group 4 Type 4A4 Issue of 1912



Chicago, IL to Appleton, WI January 27, 1914



Chicago, IL to Norwalk, OH 1914

John V. Farwell Co.

Group 4 Type 4A4 Issue of 1912





Shifted Perforations



Guideline Pair Shifted Perforations

e



Shifted Perforations Part Plate Number Imprint A5740

John V. Farwell Co. Group 4 Type 4A4 Issue of 1912



Shifted Perforations
Plate Number Imprint A5740

e



e



Guideline Strip

John V. Farwell Co.
Group 4
Type 4Å4
Issue of 1912

Largest Known Multiple



Corner Block of 16

John V. Farwell Co.
Group 4
Type 4A4
Issue of 1912

Collectors became quickly aware when a new type of perforation was first created by Farwell (Chambers) and they "requested" examples of these. Farwell, after awhile, not wanting to be bothered by this demand, supplied Type 4 sheets and other items to Chicago stamp dealer, Thomas C.E. Hunter. In return he replied to collector and dealer requests by supplying pairs, strips and blocks.







Shifted Perforations Plate Number 6151

6


Some of the stamps Hunter received had the Types 4A5 and 5A4 varieties. These varieties occurred when a pin in the second row from the top was not removed and if the sheet was inverted.

Hunter was selling the pairs at 15 cents for the 1-cent issue and 20 cents for the 2-cents issue.

Dealers received a 50% discount.




Plate Number 6151



John V. Farwell Co.

Group 4 Type 4A4 Issue of 1912



Chicago, IL to Norwalk, OH September 19, 1913




Shifted Perforations Chicago, IL December 19, 1913

John V. Farwell Co.

Group 4 Type 4A4 Issue of 1912

Pasteup



Shifted Perforations Chicago, IL to Appleton, WI April 17, 1916

Pasteup with Wide Tab



John V. Farwell Co.

Group 4
Type 4A4
Issue of 1912

Post Office Official Seal Usage



Chicago, IL March 18, 1915

Guideline




Chicago, IL September 29, 1915

John V. Farwell Co.

Group 4
Type 4A4
Issue of 1912

Only Reported Example
Type A Spacing on Left
Pasteup on Right with Type B Spacing



Chicago, IL to New London, CT March 26, 1913




Type A Spacing

Type B Spacing on Pasteup

John V. Farwell Co.
Group 4
Type 4A4
Issue of 1912

Combination of issues and private perforations



Single with 2¢ Lake Die II issue of 1906 having Schermack Type III perforations New Yok, NY to Middlebury, VT October 24, 1940

John V. Farwell Co.
Group 4
Type 4A4
Issue of 1916-1917





Shifted Perforations 2.6 mm e

(ex-Agris)

John V. Farwell Co. Group 4 Type 4A4 Issue of 1916-1917

Earliest Known Issue Usage



Chicago, IL October 24, 1916

John V. Farwell Co.

Group 4 Type 4A4 Issue of 1916-1917



Chicago, IL to Appleton, WI February 21, 1917

John V. Farwell Co.
Group 4
Type 4A4
Issue of 1916-1917

The overall majority of John V. Farwell Company mailing envelopes found was at those customer key cities, not Monona, Iowa.

Just as unusual is the Post Office Seal on the mailing and the P.O. stamped notation.




Chicago, IL to Monoma, IA March 13, 1917


Missent Envelope Two OX17 Postal Seals

(lifted/replaced)

John V. Farwell Co.
Group 4
Type 4B4
Issue of 1908-1909



Only Known Used Example Unusual Usage on non-Farwell envelope



Pair
2.6 mm
Chicago, IL to Oakland, CA
Dec? 9, 1912
e
(lifted & replaced)

John V. Farwell Co. Group 4 Type 4B4 Issue of 1908-1909



Shifted Perforations 2.4 mm



Shifted Perforations 2.6 mm

(ex-Belasco)

John V. Farwell Co.

Group 4 Type 4B4 Issue of 1910-1911





2.7 mm



Imprint Pair Shifted Perforations 3 mm



2.3 mm



Shifted Perforations 2.7 mm



Guideline Pair Shifted Perforations 2.6 mm

John V. Farwell Co. Group 4 Type 4B4

Issue of 1910-1911



U.S.POSEAGE
U.S.PO

Shifted Perforations Imprint Margin 2.6 mm e

Shifted Perforations Imprint Margin 2.6 mm



U.S.POSTAGE
U.S.POSTAGE
U.S.POSTAGE

ONE CENT
ONE CENT

Shifted Perforations 2.5-3 mm Plate Number Imprint 5484

2.6 mm Plate Number 5715



Guideline Strip 2.2-2.3 mm e



Guideline Strip Shifted Perforations 2.6 mm

John V. Farwell Co. Group 4 Type 4B4 Issue of 1910-1911



2.7 mm Plate Number Imprint A5715



2.7 mm Plate Number Imprint A5715

Mysteries of Farwell Perforation

There are several examples of Farwell perforated items that bear no clear explanation of their existence.

One is the margin items that are missing perforations. Did a Farwell employee just stop the process when he reached the last vertical row at the end of the run by accident or laziness? This variety is seen on both left and right margins and both 1-cent and 2-cent issues.

Margin Column Perforations Missing



Shifted Perforations 2.7 mm Plate Number Imprint A5679

John V. Farwell Co.
Group 4
Type 4B4
Issue of 1910-1911


One Cent Unsealed Circular Rate



Chicago, IL to Brenham, TX January 1912

John V. Farwell Co.
Group 4
Type 4B4
Issue of 1910-1911

Three Cent War Rate Unusual Usage on non-Farwell envelope



Strip Shifted Perforations Akron, OH to Benton Harbor, MI February 15, 1918

Covel Mfg Co covers are also found with John V. Farwell Co, United States Automatic Vending Co, Schermack Mailing Machine Co, Brinkerhoff Vending Machine Co and their own private perforated stamps.

One reason is that A.W. Filstrup, the president of the company was a stamp collector.

John V. Farwell Co. Group 4 Type 4B4 Issue of 1910-1911



Shifted Perforations



Pasteup



Margin Single



2.3 mm



Shifted Perforations 3 mm



Imprint Pair Shifted Perforations 3 mm



Guideline Pair 2 mm



Guideline Pair 2.6 mm

John V. Farwell Co.

Group 4
Type 4B4
Issue of 1910-1911



2.5-2.7 mm



Shifted Perforations 2.3-3.2 mm



Imprint Strip Shifted Perforations 3 mm



Guideline Strip Shifted Perforations 2.3 mm



Guideline Strip Shifted Perforations 2.7-3 mm

John V. Farwell Co. Group 4 Type 4B4 Issue of 1910-1911



Shifted Perforations 3 mm Plate Number Imprint 5624

John V. Farwell Co. Group 4 Type 4B4 Issue of 1910-1911

Earliest Known Usage



Chicago, IL to Grimms, WI then redirected to Greenleaf, WI then redirected back to Grimms, WI, then redirected to Wayside, WI

October 11, 1911

October 12, 1911

October 13, 1911

October 19, 1911

(ex-Agris)


Backstamps



John V. Farwell Co.

Group 4 Type 4B4 Issue of 1910-1911

Inverted



Chicago, IL to Milwaukee, WI January 20, 1912

> (ex-Agris) Inverted



Chicago, IL to Attleboro, MA January 29,1912 (ex-Agris)


John V. Farwell Co.

Group 4 Type 4B4 Issue of 1910-1911

Unusual Usage on non-Farwell envelopes



Shifted Perforations
Chicago, IL to Saginaw, MI December 21, 1912
(lifted & replaced)



J.M. Bartels Co.was a Stamp Dealer
Topeka, KS to New York, NY December 17, 1916

John V. Farwell Co.
Group 4
Type 4B4
Issue of 1910-1911

Thomas Hunter, as noted before, was selling Farwell's perforated stamps to dealers and collectors. His note "Chambers Perforations" was what the perforations was originally called.



Pair 3 mm Chicago, IL to Oakland, CA November 26, 1912

(ex-Belasco)

John V. Farwell Co.
Group 4
Type 4B4
Issue of 1912





Shifted Perforations



Margin Column Perforations Missing



Plate Number A5831



Guideline Pair

John V. Farwell Co.
Group 4
Type 4B4
Issue of 1912



Strip




Margin Strip Shifted Perforations

e



Guideline Strip



John V. Farwell Co.

Group 4
Type 4B4
Issue of 1912

Combination of issues with private perforations



Pair with Pairs of 1¢ and 2¢ issue of 1910-1911 having
Farwell Type 4B4 Perforations along with a Pair of 2¢ issue of 1912 with Farwell Type 4A4 Perforations
Chicago, IL to La Porte, IN
December 11, 1912
(ex-Belasco)

John V. Farwell Co.
Group 4
Type 4B4
Issue of 1912



Shifted Perforations



Pasteup 4B4 on left 4A4 on right



Shifted Perforations e

Margin Column Perforations Missing



Shifted Perforations



Guideline Pair

John V. Farwell Co. Group 4 Type 4B4 Issue of 1912



Shifted Perforations



Shifted Perforations Plate Number 5740

e




Guideline Strip


John V. Farwell Co.

Group 4

Type 4B4
Issue of 1912




Chicago, IL to Appleton, WI November 21, 1912



Chicago, IL to Attleboro, MA November 3, 1913

John V. Farwell Co.
Group 4
Type 4B4
Issue of 1912



Chicago, IL to Norwalk, OH January 18, 1913

John V. Farwell Co.

Group 4
Type 4B4
Issue of 1912

Guideline



Shifted Perforations Chicago, IL January 27, 1915



Shifted Perforations Chicago, IL November 16, 1916

John V. Farwell Co.

Group 4
Type 4B4
Issue of 1912

Only Reported Example Type B Spacing on Left Pasteup on Right with Type A Spacing



Chicago, IL February 13, 1914





Type A Spacing on Pasteup

John V. Farwell Co.
Group 4
Type 4B4
Issue of 1916-1917



Shifted Perforations Chicago, IL December 12, 1916 (lifted & replaced)



Imprint Pair Shifted Perforations e

Largest Known Multiple



Guideline Strip

John V. Farwell Co. Group 4 Type 4B4 Issue of 1916-1917



Chicago, IL to Appleton, WI February 22, 1917

John V. Farwell Co.
Group 4
Type 4A4 and Type 4B4
Issue of 1910-1911

During the perforation process the pins used to punch the holes were sometimes spaced differently in each row in an effort to center the perforations. This resulted in having both Type A and B spacing in the same row. This can be seen in the following examples.



Combination Perforations 4B4-4A4-4A4 3 mm

Combination Perforations 4B4-4A4-4A4-4A4-4A4



Margin Strip with Pressmen Initials 3 mm

John V. Farwell Co. Group 4 Type 4A4 and Type 4B4 Issue of 1910-1911



Shifted Perforations 2.6 mm Left Column Type A Center Column Type B Right Column Type B



Margin Block
Shifted Perforations
2.6 mm
Bottom Row Type A
Top Row Type B



Guideline Block Shifted Perforations 2.6 mm Bottom Row Type A Top Row Type B



Arrow Guideline Block of 8 with Pressmen Initials
Shifted Perforations
3 mm
Bottom Center Row Type A
Margin Top Column Type A
Top Center Row Type B
Margin Bottom Column Type B

John V. Farwell Co. Group 4 Type 4A4 and Type 4B4 Issue of 1910-1911



Shifted Perforations
3 mm
Plate Number Imprint A5679 with
Pressmen Initials
Top Row Type A
Middle Row Type B
Bottom Row Type B

John V. Farwell Co. Group 4 Type 4A4 and Type 4B4 Issue of 1910-1911

Combination Perforations 4B4-4A4-4A4



Pressmen Initials Shifted Perforations 3 mm

One of a few known Pasteup on any Farwell Issued Stamp



Shifted Perforations

Combination Perforations 4A4-4B4-4A4

John V. Farwell Co.

Group 4 Type 4A4 and Type 4B4 Issue of 1910-1911



Guideline Block 2.3-2.4 mm e

Top Row Type A Bottrom Row Type B



Shifted Perforations 2.3-2.4 mm Middle Row Type A Top Row Type B Bottom Row Type B



3 mm
Top Row Type B
Bottom Row Left
Column Type A
Bottom Row Middle and
Right Column Type B

John V. Farwell Co. Group 4 Type 4A4 and Type 4B4 Issue of 1910-1911



Shifted Perforations
3 mm
Top Margin Column Type A
Bottom Middle Column Type A
Bottom Right Column Type A
Bottom Margin Column Type B
Top Middle Column Type B
Top Right Column Type B



Shifted Perforations
3 mm
Top Margin Column Type A
Bottom Middle Column Type B
Bottom Right Column Type B
Bottom Margin Column Type B
Top Middle Column Type A
Top Right Column Type A



Guideline Block Shifted Perforations 2.2 mm Bottom Row Type A Top Row Type B



Center Guideline Block Shifted Perforations 2.3 mm Bottom Row Type A Top Row Type B (ex-Sheldon, Grunin)

John V. Farwell Co.

Group 4
Type 4A4 and Type 4B4

Issue of 1910-1911



Shifted Perforations 3 mm Plate Number Imprint 5608 Bottom Row Type A Top Row Type B Middle Row Type B

U.S.POSTAGE

U.S.POSTAGE

INDO CENTS

U.S.POSTAGE

Shifted Perforations
2.5-2.7 mm

Plate Number Imprint 5686
Bottom Row Type B
Top Row Type A
Middle Row Type B



Shifted Perforations
3 mm
Plate Number Imprint 5624
Bottom Row Type A
Top Row Type B
Middle Row Type B
(ex-Sheldon, Grunin)

John V. Farwell Co.
Group 4
Type 4A4 and Type 4B4
Issue of 1910-1911

Unusual Usage on non-Farwell envelope



Shifted Perforations
Philadelphia, PA to Topeka, KS
January 8, 1915
Left Margin Type A
Right Margin Type B

Thomas C. E. Hunter of Chicago was given the job of handling collector and dealer requests for Farwell perforations after the company decided not to process the same. Hunter was given 400 pairs of the 1910 Issue and 600 pairs of the 1912 Issue. It is believed that he had both the one and two cent stamps in sheet format from which he created pairs, strips and blocks.

John V. Farwell Co. Group 4 Type 4A4 and Type 4B4 Issue of 1912



Arrow Guideline Block
Shifted Perforations
Margin Top Column Type A
Bottom Middle Column Type A
Bottom Right Column Type A
Top Middle Column Type B
Top Right Column Type B
Margin Bottom Column Type B



Arrow Guideline Block Margin Top Row Type B Margin Bottom Row Type A

e



Center Guideline Block Shifted Perforations Bottom Row Type A Top Row Type B

John V. Farwell Co. Group 4 Type 4A4 and Type 4B4 Issue of 1912



Shifted Perforations Margin Row Type A Top Row Type A Middle Row Type A Bottom Row Type B Plate Number 6041



Shifted Perforations Top Row Type A Middle Row Type A Bottom Row Type B Plate Number 6041

John V. Farwell Co. Group 4

Type 4A4 and Type 4B4

Issue of 1912



Margin Strip Shifted Perforations Combination Perforations 4A4-4B4-4B4-4B4



Block Bottom Row Type A Top Row Type B



Centerline Block Shifted Perforations Bottom Row Type A Top Row Type B

John V. Farwell Co. Group 4 Type 4A4 and Type 4B4 Issue of 1912



Arrow Guideline Block
Shifted Perforations
Top Margin Left Column Type A
Top Margin Column Type B
Bottom Margin Left Column Type B
Bottom Margin Column Type A



Guideline Block Shifted Perforations Bottom Row Type A Top Row Type B



Top Row Type A
Middle Row Type A
Bottom Row Type B
Plate Number
6151

(ex-Belasco)

Margin Column Perforations Missing



Shifted Perforations
Bottom Row Type A
Top Row Type B
Middle Row Type B
Plate Number
Imprint A5785


e

John V. Farwell Co.


Group 4
Type 4A4 and Type 4B4

Type A at Left and Type B at Right

Issue of 1912



Shifted Perforations
Chicago, IL to Appleton, WI November 5, 1913



John V. Farwell Co.

Group 5
The Error Group
Type 4A5 and Type 5A4

Dealing with this Group 5, Types 4A5 and 5A4, it has been believed to had been a mistake in the early part of Farwell's development. Because of the perforation size as well as the placement of the perforating pins, the vertical spacing between the sets of perforations was either "A", 2.5mm or "B", 4.5mm, except for Group 5 which only has "A" spacing.

The company had developed a device that fed a sheet of 400 imperforated stamps into it and had a perforating arm that had rows of perforating pins on it. No one is sure if the arm had one row of perforating pins or twenty (20) rows of pins. The logical and efficient method would have been twenty rows matching the sheet size. By removing or adding these perforating pins, different combinations occurred.

If there had been only one arm then first or second row from the top of the sheet with the extra perforating pins. Then each of the other 19 rows would be same except if they found the error and fixed it.

Twenty rows of perforating pins is the most likely process. Since only the first stamp row from the sheet top was the one reportedly with the extra pin then the rest of the 19 rows would have the 4X4 perforations.

Therefore since the fifth perforating pin was only placed in the first or second row from the sheet top, there could not be any block having either Types 4A5 or 5A4 in each row of the block.

One theory regarding this Group 5 comes from Howard's book (pp. 71-72) where he mentions a letter from Vinton Sisson, someone who was dealing with the early perforations of many different company stamps, stating that Farwell had settled on the 4x4 system. But an employee who was to remove a pin from the arm to have the device produce the 4x4 perforations failed to do that. This produced a perforation that had a 4x5 configuration because he left a fifth perforating pin in the second row from the top of the sheet.

A second theory was that a full sheet of stamps were inverted being placed in the device so that the 5 holes were now on the top row and the 4 on the second row of each stamp.

A third theory comes from Belasco's book (pp. 97) where he describes a 1912 letter to C.H. Mekeel a well known dealer from a Thomas Hunter, a Chicago dealer. He thought that the 4x5 combination was produced because an employee carelessly inserted a fifth perforating pin into the second row from the top of the sheet of stamps.

If the fifth perforating pin was carelessly placed in the first row from the top of the sheet, we would then have a Type 5A4 perforation.

John V. Farwell Co.

Group 5
The Error Group
Type 4A5 and Type 5A4

All of these speculations do not explain a few of the following:.

Shown here is an example of a pair and strip with a Type 4B4 perforation in the stamp margin and Type 4A5 on the balance of the item. Was one pin not put in or the balance not pulled out?

Then there is the opposite scenario, a strip with a Type 5A4 in the left margin and the balance with Type 4B4. Here did they forget just one pin and pulled the rest, who knows?

Also there is a pair with a Type 4A5 then Type 5A4 on the balance. Did the left stamp edge have one pin added to the second row and the balance added to the top row? Do we call this a Type 4A5 or a Type 5A4?


There is a paste-up strip with a Type 4A5 in the first two columns from the left and then it is pasted to a Type 4B4 with Type 4A5 on the balance of the strip. This happens when the left stamps are at the end of a strip and then pasted to the next strip's margin.

So what is the Farwell Group 5? Is it a series of compounding errors caused by poor management, poor training of staff, carelessness or just a poorly designed piece of mechanism?

Since we see this Group 5 on the 1¢ and 2¢ issues of 1910-1911 as well as 1912, this problem may have started in 1911 when they started producing their stamp perforations, but as we see it continued on until they stopped production.

John V. Farwell Co.
Group 5

Type 4A5 Issue of 1910-1911



It occurred during the production of Group 4 when an extra perforating pin was carelessly inserted in the device in the second row of the perforating device producing the Type 4A5.

When it was accidently inserted in the first row it produced examples of Type 5A4.

This is the reason blocks would only have the extra pin hole on one row not two, neither Type 4A5 or Type 5A4 on both rows of a block.

Because of the extra 5th perforating pin the spacing between the perforation set of holes are always A Type.



2.3 mm e



Shifted Perforations 3 mm

(ex-Grunin)



2.5-2.7 mm

John V. Farwell Co. Group 5 Type 4A5 Issue of 1910-1911

This block is an example show the Type 4A5 perforations only in one row of the block.

Margin Column Perforations Missing



Shifted Perforations 2.8 mm Top RowType 4A5 Bottom RowType 4A4

John V. Farwell Co. Group 5 Type 4A5 Issue of 1910-1911



2.3 mm



Shifted Perforations 3 mm

e

Combination Perforations 4A5-4A5-4B4-4A5-4A5 Showing the left pair attached to the right pair by the margin missing a 5th pin.



Pasteup Strip Shifted Perforations



Guideline Strip Shifted Perforations 2.2-2.4 mm

John V. Farwell Co. Group 5 Type 4A5 Issue of 1912



e



Guideline Pair



Guideline Strip

John V. Farwell Co.
Group 5
Type 4A5
Issue of 1912

Only Known Used



Shifted Perforations e




(ex-Miller)



Guideline Strip

John V. Farwell Co.
Group 5
Type 5A4
Issue of 1912



It occurred during the production of Group 4 when an extra perforating pin was carelessly inserted in the device in the first row of the perforating device producing the Type 5A4.

When it was accidently inserted in the second row it produced examples of Type 4A5.

This is the reason blocks would only have the extra pin hole on one row not two, neither Type 5A4 or Type 4A5 on both rows of a block.

Because of the extra 5th perforating pin the spacing between the perforation set of holes are always A Type.



Guideline Pair Shifted Perforations

John V. Farwell Co.
Group 5
Type 5A4
Issue of 1912



(ex-Belasco)



Guideline Pair

John V. Farwell Co. Group 5 Type 4A5 Issue of 1910-1911

Farwell Group 5, the following examples also occurred.

The 5th pin missing from the second row of the margin but not the remaining stamps in the second row. Or did they forget to remove the other 19 pins.

Producing the following combination of perforations.

Combination Perforations 4B4-4A5-4A5



Margin Pair Shifted Perforations 2.7 mm

Combination Perforations 4B4-4A5-4A5-4A5



Shifted Perforations 2.6-2.7 mm

John V. Farwell Co.
Group 5
Type 4A5
Issue of 1910-1911

Farwell Group 5, the following examples also occurred.

The 5th pin missing from the second row of the margin but not the remaining stamps in the second row. Or did they forget to remove the other 19 pins.

Producing the following combination of perforations.

Combination Perforations 4B4-4A5-4A5



Shifted Perforations 3 mm

Combination Perforations 4B4-4A5-4A5-4A5



Shifted Perforations 3 mm

(ex-Sheldon, Grunin)

Group 5
Type 4A5
Issue of 1912

Combination Perforations 4B4-4A5-4A5



Margin Pair

John V. Farwell Co.

Group 5 Type 5A4 Issue of 1912

Farwell Group 5, the following examples also occurred.

The 5th pin inserted in the first row at the left but not the remaining stamps of the first row, or the 5th pin was not removed from the first row.

Producing the following combination of perforations.

Combination Perforations 5A4-4B4-4B4



e

Combination Perforations 5A4-4B4-4B4-4B4



Shifted Perforations

(ex-Sheldon, Grunin)

The 5th pin inserted in the second row at the left but also in the first row of the remaining stamps.

Producing the following combination of perforations.

So is this a 4A5 or a 5A4?

Combination Perforations 4A5-5A4-5A4



(ex-Grunin)